This Warranty does not apply to defects or damages to Products caused by human error-related factors or any other non-ordinary factors, including but not limited to:

A Malfunctions or damages caused by force majeure such as natural calamity or any inappropriate use by any person.

- B > Product has been repaired or taken apart by unauthorized technicians.
- C > Warranty label is altered, damaged or missing.

D > Product serial number does not conform to ADATA' s records, or is difficult to ascertain.

本保固條款不適用於因人為因素或非自然耗損所造成的威剛產品損壞。包括但不限於以下情形:

- A、 因天災等不可抗力因素,或人為不當操作等因素所致之損壞。
- B、 該產品經過非威剛科技授權之技術人員維修或拆裝。
- C、 該產品上的保固標籤或防拆標籤被更改、破損或遺失。
- D、 產品序號不符或序號破損、模糊不清。

以下為各產品線不予保固之標準:

The following conditions are exempt from coverage under the product warranty :


# MODULE

Warranty La	bel Issue 保固標籤異常
Alteration, removal and illegible of the type or unreadable serial number of the Product./ Product serial number does not conform to ADATA's records, or is difficult to ascertain 條碼標籤污損或不清,邊角有折入、掀起或明 顯皺褶現象或貼紙破損現象。	ADJU 1333C4G9-R DOR3 1333(9) 4GX 15 U-DIMM 1024 1556 ADATA Warranty void if removed Warranty void if removed Warranty void if removed Warranty void if removed
Label tilted or seems has been altered. 標籤貼紙翹起, <mark>有</mark> 撕過痕跡或貼紙疑似被更換 過的。	AD3S 1333C4G9-S DDR3 1333(9) 4GX16 SO-DIMM 10281352 ADATA Warranty vold if removed
ADATA warranty label missing 保固標籤貼紙遺失	

Not ADATA's product; Warranty label doesn't match with actual product 標籤貼紙與產品實物規格不符



1 × 0° × 0 ×
Skinskere Skinsk
induced damged : PBC




Connector burning (possible accompanied by PCB overheating). 金手指金屬因不當操作造成燒板異常	
Deep connector scratches Connector scratching / corrosion 金手指金屬部分嚴重損傷及裂痕。	
Connector scratched and corrosive 金手指金屬部分有腐蝕性現象。	
Repair of or modifications to the ADATA Modules not approved, authorized, or performed by ADATA. 該產品經過非威剛科技授權之技術人員維修 或拆裝,或產生的痕跡。	

## UFD


The connector bend or deformed USB 接頭變形	
Damaged and scratched on the connector or/and SN number and capacity are unrecognized. USB 接頭嚴重刮傷或是磨損無法辨識產品序號。	
USB connector cracked or broken. USB 接頭斷裂	
PCB cracked PCB板裂傷	
Not ADATA's product - inner parts are not ADATA's - Not ADATA's SN 偽品 : 實物與產品標示不符、接頭序號非威剛編 碼	
Repair of or modifications to the ADATA UFDs not approved, authorized, or performed by ADATA. 該產品經過非威剛科技授權之技術人員維修或拆裝,或產生的痕跡。。	

The housing and product are detached caused by dropping, stepping on, or otherwise mishandling the product during installation. 產品因不慎掉落以致外殼與零件分離現象,及 安裝過程中的人為損壞。



#### CARD






#### HDD





Physical induced damaged in the inner disk / Inner disk has concave or convex mark. 內部裸碟變形。






## SSD - Solid State Drives







## **POWER BANK**



### LIGHTNING CABLE

