

Platform suggestions and permission requirements:

- ADATA Solid State Drive Firmware Update Tool can be used on Windows 7 / Vista / XP, as well as Fedora Core 12 64-bit and Fedora Core 14 32-bit computer systems. It does not support Mac OS.
- 2) You must have Administrator rights in order to run the Field Updater.

Reminder:

1) Updating the firmware will clear the data stored in the SSD. It is *extremely important* that you *back up your data* before updating the SSD firmware.



Step 1-

Go to the ADATA website and find your corresponding product model. Click on the firmware version you need. (Example: Firmware 5.0.7a)

Program

Description	Language	OS	File Size (KB)	Update	Download
Firmware Upgrade Tool	English	Linux 32-bit	4.22MB	2011-11-30	Download
Firmware 5.0.7a	English	Windows 7 / Windows XP / Windows Vista / Window 8	14.7MB	2013-04-19	Download

Step 2- Decompress the downloaded firmware file and find the program named

"ADATA_SF_FieldUpdater". Open this executable file to start the firmware update.

					R		x
(3) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	(磁磁區 (E:)			▼ 49 授辱 新增	据强置(E)		Q
組合管理 ▼ 🗐 開設	新道篮科奕				3	•	0
🗙 我的最爱 🤺	名稱	日期	Ť	頓型	大小	標記	
👪 मंड	ADATA_SF_FieldUpdater	2011	/8/30 下午 01:16	應用穩式	6,940 KB		
100 桌面 120 最近的位置							
○ 然證櫃 □ ○ ○ ○ ○ ○ □ ○ □ ○ □ ○ □							
			Find and	run			
달 여파 달 원부			ADATA_S	F_FieldUpd	ater		
🍋 電腦							
🏭 本機磁碼 (C:)							
□ 本機磁碼 (D.)							
□ 新增磁硬區(E) ↓ <			II.				•
ADATA_SF_FieldU 座用程式	Updater 修改日期: 2011/8/30 下午 01:16 大小: 6.77 MB	建立日期: 2012/6/20下	5年 05:43				



ADATA_SF_FieldUpdater			
Field Updater	Serial No.	AL	
		This is the star	t screen of
		ADATA_SF_Fiel	dUpdater
Detected Drives			
List of supported drives detected on your system. operation.	. Please put a check mark to the driv	ves that you want update. Click on drive	icon to see the output from the last
Update Furnware Restan For Drives			About Exit

Step 3- If your SSD does not appear in the Field Updater when the program starts, click "Rescan for Drives in order to for the program to successfully detect system SSDs.

ADATA_SF_FieldUpdater				- • ×
Field Updater			ADA	ΓA [™]
All Model	Serial No.	FM Rev. Signature	- Ca	pacity (GB)
			_	
Detected Drives	Click "Rescan For	Drives"		
List of supported drives detected on your system. operation.			t on drive icon to see the o	utput from the last
Updale Firmware Restan For Drives			Â	hoot Exit



1 Model		Serial No.	FW Rev. Sign	ature	Capacity (GB)
	Scanning	For Drives. Ple	ease wait		
			Star ADA	t scanning for ATA_SF_FieldU	drives of pdater



Step 4- When the SSD has been detected and displayed, select the drive(s) to be updated and then click "Update Firmware" to start the update.

Note: If you want to update more than one drive at a time, make sure the Signature field in the Field Updater has the same last five digits for each SSD.

ROTE .	NOVEL	Seri	al No.	FM Rev.	Signature	Capacity (GB)
2005	IMITA SP900	1208	0600000000000000	6.9.20	168-0-22789	53-68
			Wh	ien Re	scan is finished	d, you
			wil	l see h	ere all current	SSDs.
ie Help				NY 26 5 10 - 10 - 17	2,4307,9760	
ie Help is the a	line help for any of the items i	in this window, plaase m	ove your mouse ave	r the item o	of interest.	
ne Help va the or lpdsk Fo	sline help for any of the items i means	in this window, please m žves	ove your mause ave	r the item (f interest.	Àbout.
ne Help the or Iplate Fo	nline help for any of the items i myses	in this window, please m	ove your mouse ava	r the item o	of interest.	Àbout.

Field Updater			A	DATA
All Model	Serial No.	FW Rev.	Signature	Capacity (GB)
Check to upgrade of this SSD	the firmware	5.0.2b	158-0-22739	59.63
Detected Drives List of supported drives detected on your system. Please put operation.	Click "Updat the lower left	e Firm t corn	nware" in er to start	icon to see the output from the last
Update Firmware	update.			About Exit



Step 5- When you press "Update Firmware", the program will ask you to choose the Firmware number. Then provide the path to the folder where you have downloaded the file. Find the Firmware with the same number and click twice to go to the next step of the update.

Note: Your firmware number can be seen in the Field Updater Signature field, it is the last five digits.

1	AD	ATA_SI	F_FieldUpdater				
		F	ield Updater			AD	ATA
	A11		Model	Serial No.	FW Rev.	Signature	Capacity (GB)
	v	S.	ADATA SP900	120606000000000	0031 5.0.2ъ	158-0 <mark>-22739</mark>	59.63
				Select Firmware File ○○○○○●● 電腦 組合管理 ▼ 新増資	▶ 新増磁碟屋 (G;) • 5.0.2b • •	
				名稱		修改日期	項型 大小
				22739.vic		2012/6/18 下午 0 V	/IC 檔案 441 KB
				22790.vic		2012/6/18 下午 0 V	/IC 檔案 441 KB
	Upd	ate Fi	mware		Select the five digits Signature	e file that has the s as the Field Upc e field.	e same last Jater
	Upda	Update I	e firmware on the selected drives above. You Firmware Rescan For Drives	L 福	案名稱(N): 22739	9.vic 🗸 Su	upported files (*.vic *.FFP) ↓ 開啟酱橘(O) 取消



Step 6- When you successfully found and clicked on the corresponding Firmware number, the program will display an alert window. Click the "Proceed" button to start the update.

Note: When you update the firmware, do not close the Field Updater, and make sure the solid state drive and the computer remain connected until the firmware update is complete.

ADATA_SF_FieldUpdater									
Field Upd	ater	4	NDA	TA™					
All Model	Serial No.	FW Rev. Signature		Capacity (GB)					
ADATA SP900	1206060000000000031	5.0.2b 158-0-2273	9	59.63					
Warning A d If o	Warning Automatic restart may occur after this operation. You should save all unsaved data before proceeding. If you wish to cancel the operation and save unsaved data now, click Cancel, otherwise click Proceed. Proceed Cancel								
Detected Drives List of supported drives detected on operation. Update Firmware Resce	ı your system. Please put a check mark to the drives t an For Drives	that you want update. Cli	ck on drive eee th Press "Pro perform th	ne output from the last ceed" to ne update.					



Step 7- Congratulations! You have successfully updated your

firmware!

Note: To ensure that your update was effective, click the lower left corner "Rescan For Drives" box and re-scan your SSD and Firmware versions. Confirm that your SSD now displays the desired version.

9		SF_FieldUpdate	r						X
		Field	Updater				AD/	АТ.	A
	A11	Model		Seri	al No.	FW Rev.	Signature	Capaci	ty (GB)
	V 🛓	ADATA SP90	D	1206	0600000000000031	5.0.2b	158-0-22739	59.63	
	Detect List of s operatio	ed Drives upported drives o n. ate Firmware	letected on your system. Plea Rexan For Drives	ise put a ch	Click Resc that your desired Fi	an For SSD nc rmwar	Drives to ensure ow has the e version.	see the output	from the last

